


BDHS Facility Concerns


Career & Technical Education



The career and technical education wing is approaching 40-years-old and does not allow for real-life work experiences in a school setting.

Locker Rooms & Outdoor Restrooms

Locker rooms for female students are 30% smaller than facilities for male students. BDHS does not have outdoor bathroom facilities.




General Classrooms



Many classrooms have remained untouched since 1958. They have asbestos floors & ceilings, poor lighting, damaging acoustics, falling ceilings, poor ventilation and inadequate electrical capacity.

Cafeteria & Kitchen

The current cafeteria & kitchen areas were designed to accommodate 800 people, they now serve 1,100. Supervision of students is difficult, current layout limits community use.



Infrastructure



Mechanical systems are approaching 40-years-old. Old boilers need to be removed. Heating, cooling, electrical and plumbing needs total \$7.7 million.

Safety/Security

All schools need modified/relocated entrances. Current designs do not reflect 2016 safety and security needs.



Leading the way in student growth and achievement.